



DEPARTMENT OF THE ARMY

U.S. Army Corps of Engineers
WASHINGTON, D.C. 20314-1000

24 JUN 1991

SEP 17 RECD

REPLY TO
ATTENTION OF:

CECW-ON

MEMORANDUM FOR ALL MAJOR SUBORDINATE COMMANDS

SUBJECT: Shoreline Management Flotation Requirements

1. We have discovered a technical error in Appendix C to 327.30 - Shoreline Use Permit Conditions published in the Federal Register on 27 July 1990. Condition 14 is incorrect. There is no extruded polystyrene or styrofoam material that is resistant to petroleum products.
2. We plan to publish a change to the final rule in the Federal register which will correct this problem.
3. We will reevaluate the requirement to replace all foam bead flotation as it becomes unserviceable. If needed, we will issue additional guidance concerning flotation for structures covered by the Shoreline Management Regulation.
4. In the interim, if flotation materials covered by the Shoreline Management Regulation become unserviceable you may continue to use prior requirements to guide replacement.

FOR THE DIRECTOR OF CIVIL WORKS:

JOHN P. ELMORE
Chief, Operations, Construction
and Readiness Division
Directorate of Civil Works